Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 9/5/2014	Man Days: 1
Inspection Unit: Maryville	·
Location of Audit: Caseyville	
Exit Meeting Contact: Charles Tebbe	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

	Email:	
	Phone#: (217) 424-6518	
Official or Mayor's Name:	Ron Pate	
	Fax#:	
	Emergency Phone#: (800) 755-5000	
	Peoria, IL 61602	
Headquarters Address Information:	300 Liberty	

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
Staff only witnessed an annu- replace the worn diagrams ar	al exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew dis nd do a lock up check.	sable the station and
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Checked
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Checked
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Checked
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Checked
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Checked
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Checked
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Checked
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
[192.727(d)][192.72	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Checked
	CATHODIC PROTECTION	Status
Category Comment:		
	annual exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew disams and do a lock up check.	able the station and
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Not Checked
[192.465(a)]	Were pipe to soil readings taken?	Not Checked
[192.465(b)]	Were rectifier installations inspected?	Not Checked
[192.465(a)]	Were isolated mains/services tested?	Not Checked
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Not Checked
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
[192.479(a)]	Is the above ground piping coated or painted as required?	Not Checked
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Not Checked
	DAMAGE PREVENTION	Status
Category Comment:	·	
	annual exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew disams and do a lock up check.	able the station and
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Not Checked
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Not Checked
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Not Checked
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Not Checked
PRESSURE	LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
General Comment: The compliance date for this in	nspection is 12/31/14.	
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
General Comment:		
Station CH 038 was protected	from accidental damage by the use of a locked fence.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Satisfactory
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will	Satisfactory

AMEREN ILLINOIS COMPANY/9-5-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	make the pressure relief valve or pressure limiting device inoperative?	
	VALVE MAINTENANCE	Status
Category Comment:		
	annual exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew dis- ms and do a lock up check.	able the station and
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Not Checked
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Checked
	ODORIZATION OF GAS	Status
Category Comment:		
	annual exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew disams and do a lock up check.	able the station and
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Satisfactory
General Comment:	<u>.</u>	
The Ameren crew used	a FI unit. The unit number was 10185 and was calibrated on 8/9/14 and is due on 9/15/14.	
	TRANSMISSION	Status
Category Comment:		
Staff only witnessed an replace the worn diagram	annual exam performed by an Ameren crew for regulator station CH 038. Staff witnessed the Ameren crew dis- ms and do a lock up check.	able the station and
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked
[192.745(a)]	Were the valves inspected accessible?	Not Checked
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
MARKING OF MATERIAL		Status
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Satisfactory
	OPERATOR QUALIFICATION	Status
Was a PHMSA For	m 15 Operator Qualification Field Inspection Protocol Form completed?	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

AMEREN ILLINOIS COMPANY/9-5-2014 Page 5 of 5